

**PRELIMINARY ASSESSMENT/SITE INSPECTION REPORT
AND SWMU ASSESSMENT REPORT**

UNIT NUMBER:	229
UNIT NAME:	OS-18
DATE:	12/01/00
REGULATORY STATUS:	SWMU
LOCATION:	North of C-746-F
APPROXIMATE DIMENSION:	48,000 ft ² .
FUNCTION:	Originally used to store excess railroad materials then became an area in which to store various excess material.
BRIEF HISTORY:	Established soon after plant construction to store excess railroad supplies, parts, components, etc.
OPERATIONAL STATUS:	Active
DATES OPERATED:	Probably in 1950 to present
SITE/PROCESS DESCRIPTION:	Storage area for excess railroad supplies and other materials.
WASTE DESCRIPTION:	Scrap metal, concrete, two small huts/buildings, trash cans, railroad ties, fans, chain link fencing, and parts from railroad cars.
WASTE QUANTITY:	20,500 ft. ³
SUMMARY OF ENVIRONMENTAL SAMPLING DATA:	None Identified

DESCRIPTION OF RELEASE AND MEDIA AFFECTED: None known

GROUNDWATER: N/A

SURFACE WATER: N/A

SOIL: N/A

ECOLOGY AFFECTED (i.e., endangered/threatened species) None

DOCUMENTATION OF NO RELEASE: None

IMPACT ON OR BY OTHER SWMU/AOC: SWMUs 5, 6, 13, and 227 are located nearby.

PRG COMPARISON: N/A

RFI NECESSARY: Yes

NOTE: Elements included in this outline shall be considered and incorporated, as appropriate, when developing the above referenced document.